

# Additel 680A & 680AEx & 680P Digital Pressure Gauge



Gauge Pressure													
P/N	Pressure Range		Display Resolution										
	(psi)	(bar)	psi	Pa	KPa	MPa	bar	mbar	kgf/cm <sup>2</sup>	inH <sub>2</sub> O@4°C	mmH <sub>2</sub> O@4°C	inHg@0°C	mmHg@0°C
V15	-15	-1.0	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.01	1	0.001	0.01
GP5	5	0.35	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.01	1	0.001	0.01
GP10	10	0.7	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.01	1	0.001	0.01
GP15	15	1.0	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.01	1	0.001	0.01
GP30	30	2.0	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.01	1	0.001	0.1
GP50	50	3.5	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.1	1	0.01	0.1
GP100	100	7.0	0.01	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.1	1	0.01	0.1
GP150	150	10	0.01	N/A	0.1	0.0001	0.001	1	0.001	0.1	N/A	0.01	0.1
GP300	300	20	0.01	N/A	0.1	0.0001	0.001	1	0.001	0.1	N/A	0.01	1
GP500	500	35	0.01	N/A	0.1	0.0001	0.001	1	0.001	1	N/A	0.1	1
GP600	600	40	0.01	N/A	0.1	0.0001	0.001	1	0.001	1	N/A	0.1	1
GP1K	1,000	70	0.1	N/A	0.1	0.0001	0.001	1	0.001	1	N/A	0.1	1
GP1.5K	1,500	100	0.1	N/A	1	0.001	0.01	N/A	0.01	1	N/A	0.1	1
GP2K	2,000	140	0.1	N/A	1	0.001	0.01	N/A	0.01	1	N/A	0.1	N/A
GP3K	3,000	200	0.1	N/A	1	0.001	0.01	N/A	0.01	1	N/A	0.1	N/A
GP5K	5,000	350	0.1	N/A	1	0.001	0.01	N/A	0.01	N/A	N/A	1	N/A
GP10K	10,000	700	1	N/A	1	0.001	0.01	N/A	0.01	N/A	N/A	1	N/A
GP15K	15,000	1,000	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	1	N/A
GP20K	20,000	1,400	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	1	N/A
GP25K	25,000	1,600	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	1	N/A
GP30K	30,000	2,000	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	1	N/A
GP36K	36,000	2,500	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	1	N/A
GP40K	40,000	2,800	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	1	N/A
GP50K	50,000	3,500	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	N/A	N/A
GP60K	60,000	4,200	1	N/A	N/A	0.01	0.1	N/A	0.1	N/A	N/A	N/A	N/A

# Additel 680A & 680AEx & 680P Digital Pressure Gauge



Metrology Made Simple

Compound Pressure													
P/N	Pressure Range		Display Resolution										
	(psi)	(bar)	inH <sub>2</sub> O@4°C	mmH <sub>2</sub> O@4°C	psi	Pa	KPa	MPa	bar	mbar	kgf/cm <sup>2</sup>	inHg@0°C	mmHg@0°C
CP5	± 5	±0.35	0.0001	1	0.001	0.0001	0.0001	0.01	0.0001	0.01	0.1	0.001	0.01
CP10	± 10	±0.7	0.001	1	0.001	0.0001	0.0001	0.01	0.0001	0.01	0.1	0.001	0.01
CP15	± 15	±1	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.01	1	0.001	0.01
CP30	- 15 to 30	-1 to 2	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.1	1	0.01	0.1
CP50	-15 to 50	-1 to 3.5	0.001	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.01	1	0.001	0.1
CP100	-15 to 100	-1 to 7	0.01	N/A	0.01	0.0001	0.0001	0.1	0.0001	0.1	1	0.01	0.1
CP150	-15 to 150	-1 to 10	0.01	N/A	0.1	0.0001	0.001	1	0.001	0.1	N/A	0.01	0.1
CP300	-15 to 300	-1 to 20	0.01	N/A	0.1	0.0001	0.001	1	0.001	0.1	N/A	0.01	1
CP500	-15 to 500	-1 to 35	0.01	N/A	0.1	0.0001	0.001	1	0.001	1	N/A	0.1	1
CP600	-15 to 600	-1 to 40	0.01	N/A	0.1	0.0001	0.001	1	0.001	1	N/A	0.1	1
CP1K	-15 to 1,000	-1 to 70	0.1	N/A	0.1	0.0001	0.001	1	0.001	1	N/A	0.1	1