



1. AC Input




Wire clamp connector.

2. DC Output






Output terminals for 6V to 60V models.




Output terminals for 100V to 600V models.

1. Connect the AC power cord wires to the AC input terminals.

- Black/Brown → Line (L)
- White/Blue → Neutral (N)
- Green /Green & Yellow → Ground (⊥)








Connection  
 Example  
 (PSU 6-200, 12.5-  
 120, 20-76, 40-38,  
 60-25)

Use the included M8-sized bolt set to connect the load cables to the output terminals. Make sure that the connections are tight and that washers and spring washers are used to ensure a good connection.



M8 규격의 볼트체결 방식, M8의 HOLE 은 18.65mm 입니다.